

# GAS LINE 137B GANNON SLOUGH EROSION CONTROL PROJECT

PACIFIC GAS AND ELECTRIC COMPANY

Arcata, CA



## Project Description

Gas Line 137B Gannon Slough Erosion Control Project, Arcata, CA  
Gannon Slough is a tidal slough located near the City of Arcata along highway 101 in Humboldt County. A gas pipeline was exposed by erosion and ERCON intends on covering the exposed pipe with a concrete blanket for protection. The following tasks describe the planned activities:

Transcon assisted PG&E in covering a gas pipeline exposed by erosion along Highway 101 in Arcata, California. The tasks performed by Transcon included, Preparing submittals and gaining approval for various permits, conducting biological and cultural resources surveys and writing reports on data gathered in the field, preparation of a rare plant revegetation plan and mitigation for loss of riparian/wetland/stream channel habitat, coordinated with various agencies and provided weekly tracking for project updates.

## Agency Coordination

US Fish and Wildlife Service, National Marine Fisheries Service, US Army Corps of Engineers, State Water Quality Control Board, California Department of Fish and Game, California Coastal Commission, Humboldt Bay Harbor and Recreation District, and City of Arcata

